DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012187 Address: 333 Burma Road **Date Inspected:** 18-Feb-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Li Yang **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Weld Procedures Followed:** N/A **Electrode to specification:** No Yes No Yes N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girder (OBG)

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Manoj Prabhune was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG # TRIAL ASSEMBLY YARD

This QA Inspector randomly observed the following work in progress:

Segment# 7AW-PP49

This QA inspector observed, ZPMC qualified welding personnel identified as 068917 perform Shielded Metal Arc Welding (SMAW), weld joint identified as SP124-001-037; ZPMC CWI is identified as Mr.Li Yang. The welding parameters measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2213-B-U2. See the attached below Photo

Segment # Cross Beam-6/6CE-PP45

This QA inspector observed, ZPMC qualified welding personnel identified as 066261 perform Shielded Metal Arc Welding (SMAW), weld joint identified as FB032-001-128; ZPMC CWI is identified as Mr.Li Yang. The welding parameters measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2212-TC-U4b-FCM-1. See the attached below Photo.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Segment # Cross Beam-6/6CE-PP45

This QA inspector observed, ZPMC qualified welding personnel identified as 067665 perform Shielded Metal Arc Welding (SMAW), weld joint identified as SSB17-PP45-166; ZPMC CWI is identified as Mr.Li Yang. The welding parameters measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2114.

This QA inspector observed, ZPMC qualified welding personnel identified as 220066 perform Flux Core Arc Welding (FCAW), weld joint identified as OBW6F-010; ZPMC CWI is identified as Mr.Li Yang The welding parameters measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2233T.

Segment

Repair Welding.

This QA inspector observed, ZPMC qualified welding personnel identified as 037743 perform Shielded Metal Arc Welding (SMAW), weld joint identified as SEG027F-008; The Welding Repair Report (WRR) was B-WR10627. ZPMC QC is identified as Mr.Li Yang. The welding parameters measured using QC's calibrated instrument appeared to be in general compliance with WPS-345-FCAW-1G (1F) Repair.





Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang phone: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Prabhune, Manoj	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer